CIVIL AVIATION AUTHORITY

CAA SUPPLEMENT NO 4 ISSUE 1 TO THE CESSNA 310 OWNERS MANUAL D983



(CAA Ref: 1650/55029)

Serial No:

Registration Mark:

ADDITIONAL LIMITATIONS AND INFORMATION FOR UNITED KINGDOM CERTIFICATION

The limitations and information contained herein either supplement or, in the case of conflict, override those in the flight manual.

AERONAUTICAL TESTING SERVICES Inc. VORTEX GENERATOR KIT (STC SA5756NM)

The ATS Inc. modification consists of ninety (90) vortex generators mounted on the wings and vertical fin and four (4) metal strakes, one mounted on the inboard and one mounted on the outboard side of each engine nacelle.

LIMITATION

If any strake or more than six vortex generators are missing or damaged, the aircraft must be repaired before flight.

- End -

To be inserted at the back of the owners manual and the CAA Revisions Record Sheet amended accordingly

Page 1 of 1

CAA Approved 1 February 2002